

AP722309_Berry fürdőszobai mérleg

FRONT PART

AP722309_Berry fürdőszobai mérleg Használati útmutató (Hun)



Javasoljuk, hogy figyelmesen olvassa el ezt a használati utasítást és tartsa meg a jövőbeli felhasználáshoz.

Termék nézet:



ON / OFF / Egységek

Jellemzők:

Maximum súly: 180kg
Minimum súly: 0.2kg
Pontosság: 50g
Mértékegységek: kg/lb
Hőmérséklet
Automatikus bekapcsolás, ON/OFF funkció

Működtetés:

Helyezzen bele 2 AAA elemet a mérleg hátuljában lévő részbe.

A mértékegység megváltoztatásához nyomja meg az ON/OFF gombot.

A mérleg automatikusan bekapcsol, ha a súly meghaladja a 4 kg-ot. A képernyő automatikusan megjeleníti a hőmérsékletet, súlyt, és a töltöttség állapotát.

A képernyő kikapcsol automatikusan 15 másodperc után.

Figyelmeztetések:

1. Ne tegye ki az eszközt esőnek vagy nyirkos környezetnek.
2. Előzze meg, hogy az eszköz leessen, mert az komoly sérüléseket okozhat.
3. Ne szedje szét, ne javítsa és ne alakítsa át az eszközt önállóan, lépjen kapcsolatba szakemberrel.
4. Hogy minden kockázatot elkerüljön, ne dobja az eszközt helytelen szemetesbe.
5. Száraz ruhával takarítsa az eszközt.
6. Ne tegye az eszközt közvetlen hőforrás mellé vagy közvetlen napsugárzásnak.
7. Ne tegyen semmiféle fém eszközt a készülékbe, mert rövidzárlatot okozhat.



Ez a szimbólum azt jelenti, hogy az eszköz elektromos élettartamának lejártán az Ön háztartási hulladékaitól elkülönítetten kell újrahasznosítani. Ennek megfelelően dobja a kijelölt hulladékgyűjtőbe. További információkért hívja a helyi hatóságokat.

Forgalmazó: Cool collection, Budapest Pf.:176,
1476, Magyarország
Cégjegyzékszám: 01-09-276783
Származási ország: Kína

BACK PART

AP722309_Weighing Scales Berry User manual(Eng)



It is recommended to read this user manual carefully and keep it for future reference.

Product overview:



ON/OFF / Units

Specifications:

Maximum capacity: 180kg
Minimum capacity: 0.2kg
Accuracy: 50g
Units of measurement: kg/lb
Temperature
Auto power ON/OFF function

Operation:

Insert 2 button batteries AAA and place the scale onto a firm level surface.

To change the measurement units, press the ON/OFF button.

The scale will turn on automatically with a weight higher than 4kg. The screen will show the weight, the temperature and the battery level.

The screen will turn off automatically after 15 seconds.

Warnings:

1. Do not expose this product to rain or damp conditions.
2. Prevent this item from falling as it could cause serious damage.
3. Do not dismantle, repair or modify this product by yourself, contact an authorized specialist.
4. In order to avoid any risk, do not dispose of this product inappropriately.
5. Clean it with a dry cloth.
6. Do not place this item near sources of heat or expose to direct sunlight.
7. Do not insert any metal objects into this device as there is a risk of causing a short circuit in the unit.



This symbol both in the product and its user manual indicates that at the end of the devices electrical life, it should be recycled separately from your household waste. There are adequate means to dispose of this material for proper recycling. For more information, contact your local authorities.

Distributor: Cool collection, Budapest Pf.:176, 1476, Hungary
Registration number: 01-09-276783
Country of origin: China